

Roll No.

Total Pages : 03

013402

May 2024

B.Tech. (ME/ME(Hindi) (Fourth Semester)

Materials Engineering (PCC-ME-402-21)

Time : 3 Hours]

[Maximum Marks : 75

Note : It is compulsory to answer all the questions (1.5 marks each) of Part A in short. Answer any *four* questions from Part B in detail. Marks and related course-outcome are given against each question.

Part A

1. (a) Name any *three* properties of Engineering materials. 1.5
- (b) What do you mean by slip system in any crystal ? Give one example. 1.5
- (c) How do edge dislocations interact with each other in crystals ? What is meant by dislocation annihilation ? 1.5
- (d) List any *three* methods of materials strengthening. 1.5
- (e) Illustrate three types of dynamic stress cycles with the help of sketches. 1.5

CT-04
26

- (f) List any *three* factors that affect the creep deformation in materials. 1.5
- (g) What do you understand by interstitial solid solution? Give one such example. 1.5
- (h) Write down Gibbs Phase rule. What is the significance of this rule in materials engineering? 1.5
- (i) Name any *three* applications of Biomaterials. 1.5
- (j) What are Shape Memory Alloys (SMAs)? List some applications of SMAs. 1.5

Part B

2. (a) Briefly explain the family of cubic crystal directions and planes by giving suitable examples. 8
Convert the Miller Indices [112] into Bravais Miller Indices (Four indices system).
- (b) Rhodium has an atomic mass of 103 g/mol, atomic radius of 0.1345 nm and a density of 12.41 g/cm³. Determine whether it has an FCC or BCC structure. Take Avagadro's Number as 6.022×10^{23} per mol. 7

3. (a) Explain the plastic deformation in polycrystalline materials with the help of stress strain curve. 7.5
- (b) Discuss in detail the deformation by twinning mechanism in crystalline materials with neat sketches. 7.5
4. (a) Differentiate between the ductile and brittle fracture. 7.5
- (b) Explain in detail the fatigue fracture in metals and alloys. 7.5
5. (a) The mass fraction of total ferrite and total cementite in an iron-carbon alloy is 0.91 and 0.09 respectively. Is this a hypoeutectoid or hypereutectoid alloy? Why? 7.5
- (b) Classify and describe solid solutions with suitable examples and sketches. 7.5
6. Discuss in detail different types of heat treatment processes for steels. 15
7. Write short notes on the following :
- (a) Composite materials 7.5
- (b) Economic, environmental, and societal issues in materials engineering. 7.5